

### ABSTRACT

A method of patterning electrically conductive polymers is: forming a surface of a conducting polymer on a substrate, applying a mask to this surface, applying irradiation to form regions of exposed conducting polymer and regions of unexposed conducting polymer, removing the mask, and gently removing by non-chemically reactive means the regions of exposed conducting polymer.